

Company: Century Aluminum Of Kentucky, LLC
 Address: P.O. Box 500
 Hawesville KY 42348

RCRA Report, Part I

Complete Facility Report

The manufacturer MSDS indicates that the following products contain materials which have been assigned Acute Hazardous Waste Codes under provisions of the Resource Conservation and Recovery Act.

| Tradename | Manufacturer | MSDS Date | Chemical Component | % Mix | Code |
|---|----------------------------------|------------|--------------------|--------------|------|
| 965AP-G, BUILD UP AP-G, TTX-1 AP-G | STOODY CO. | 3/20/2002 | vanadium | 1,314,621.00 | P120 |
| ALLOYED ALUMINUM 358.2 | CENTURY ALUMINUM OF KENTUCKY LLC | 7/2/2001 | beryllium | 7,440,417.00 | P015 |
| ALUMINUM , BERYLLIUM MASTER ALLOY | KB ALLOYS, INC. | 12/16/1986 | beryllium | 7,440,417.00 | P015 |
| ARSENIC REFERENCE STD SOL, SA449100 | FISHER SCIENTIFIC | 3/4/1996 | arsenic trioxide | 1,327,533.00 | P012 |
| BATH (ELECTROLYTIC), ALUMINUM REDUCTION | NORANDA ALUMINUM, INC. | 2/27/2003 | beryllium | 7,440,417.00 | P015 |
| BERYLLIUM ALUMINUM MASTER ALLOY | BRUSH WELLMAN INC. | 1/12/1990 | beryllium | 7,440,417.00 | P015 |
| BESLY/THREADWELL CUTTING TOOLS | BESLY PRODUCTS CORP. | 5/1/1997 | vanadium | 1,314,621.00 | P120 |
| CARTRIDGE FOR POWER DEVICE | OLIN CORP. | 8/17/1993 | nitroglycerin | 55,630.00 | P081 |
| COMPOSITE WIRE-100,101,103,117,121,... | STOODY CO. | 11/28/2001 | vanadium | 1,314,621.00 | P120 |
| COMPOSITE WIRE-TRACKWEAR,NICROMANG, 110,. | STOODY CO. | 7/9/2003 | vanadium | 1,314,621.00 | P120 |
| COPPER SCRAP | MANITOBA | 7/8/1998 | beryllium | 7,440,417.00 | P015 |
| CRUSHED ELECTROLYTIC BATH | COLUMBIA FALLS ALUMINUM CO. | 1/1/1985 | beryllium | 7,440,417.00 | P015 |
| HALL CELL BATH WITH | ALCOA INC. | 10/20/2000 | beryllium | 7,440,417.00 | P015 |
| HIGH SPEED STEEL DRILL BIT | PRECISION TWIST DRILL COMPANY | 9/1/1991 | vanadium | 1,314,621.00 | P120 |
| LOW ALLOY STEEL | GERDAU | 5/1/2006 | vanadium | 1,314,621.00 | P120 |
| METAL & METAL ALLOYS OF AL,CO,NI,LE & ST | INTEGRIS METALS | 1/1/2002 | beryllium | 7,440,417.00 | P015 |
| MILWARD 5% BERYLLIUM | MILWARD ALLOYS, | 10/16/1998 | beryllium | 7,440,417.00 | P015 |
| MOLTEN ALUMINUM | CENTURY ALUMINUM OF KENTUCKY LLC | 7/2/2001 | beryllium | 7,440,417.00 | P015 |
| PHOSPHOR BRONZE-C, 23 | HARRIS-WELCO | 1/5/1998 | fluorine | 7,782,414.00 | P056 |
| SPENT POTLINING | ALUMINUM CO. OF AMERICA | 12/20/1994 | phosphine | | P096 |

Company: Century Aluminum Of Kentucky, LLC
Address: P.O. Box 500

Hawesville KY 42348

RCRA Report, Part I

Complete Facility Report

The manufacturer MSDS indicates that the following products contain materials which have been assigned Acute Hazardous Waste Codes under provisions of the Resource Conservation and Recovery Act.

| Tradename | Manufacturer | MSDS Date | Chemical Component | % Mix | Code |
|------------------------|---------------------------------|-----------|------------------------|--------------|------|
| TOTAL CYANIDE | ANALYTICAL PRODUCTS GROUP, INC. | 1/31/2004 | potassium ferricyanide | 151,508.00 | P098 |
| VASCO SPECIALTY STEELS | TELEDYNE VASCO | 4/1/1990 | vanadium | 1,314,621.00 | P120 |

This information is provided to assist you in managing wastes that may be generated by your facility. Each facility has the responsibility for determining the status of waste streams at the time of disposal.